

# National Inspection Services

Report: 261401 04/10/2024

VIN: 1FUJGLD51GLGS5857

Stock #: 14440

### Commercial Credit Group, Inc (Mark Wenzel) 525 N Tryon Street, Charlotte, NC 28202 USA (704) 414-2456

## 2016 FREIGHTLINER CASCADIA

	SPECIFICATIONS
MILEAGE	466,813 / 466,813 (ECM)
ENGINE HOURS	15,314
ENGINE	DETROIT DD15 14.8L 455 HP
ENG BRAKE	YES
ENG SERIAL	472906S0302597
FUEL / TANKS	DIESEL - 2 ALUM 200 GAL TOTAL
EXHAUST	SINGLE
TRANSMISSION	DETROIT DT12 DA 1750-HD 12 SPD AUTO
DRIVE OPTS	POWER STEERING, OVERDRIVE, CRUISE
REAR END	DETROIT 3.23
AXLE TYPE	TANDEM - F 13,220 LB / R 40,000 LB
GVWR	53,220
FRAME	STEEL
SUSPENSION	AIR RIDE
WHEELBASE	238"
TIRE SIZE	11R22.5
WHEELS	F STEEL / R STEEL
WHEEL 5TH	AIR SLIDE
AIR COND	YES, OPERATIONAL
AUX POWER UNIT?	YES
SLEEPER	72"
DUAL BUNK	YES
INTERIOR COLOR	GREY
RADIO	AM/FM, OPERATIONAL
MIRRORS	DUAL POWER
HIGH BACK SEATS	DUAL
PASSENGER SEAT	AIR RIDE
EXTERIOR COLOR	WHITE
BUMPER	PLASTIC
EXTERIOR OPTS	HEATED MIRRORS, ROOF FAIRINGS
COLLISION AVOIDANCE?	NO



BRAKES		
LEFT FRONT	RIGHT FRONT	
COVERED	COVERED	
LEFT REAR 1	RIGHT REAR 1	
COVERED	COVERED	
LEFT REAR 2	RIGHT REAR 2	
COVERED	COVERED	

TIRES & WHEELS				
LEFT FRONT 19 / 32 STEEL		RIGHT FRONT 18 / 32 STEEL		
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1	
16 / 32 CONTINENTAL STEEL	5/32 BRIDGESTONE STEEL	18 / 32 BRIDGESTONE STEEL	14 / 32 CONTINENTAL STEEL	
LEFT OUTER 2	LEFT INNER 2	RIGHT INNER 2	RIGHT OUTER 2	
11/32 BRIDGESTONE STEEL	10 / 32 BRIDGESTONE STEEL	11/32 CONTINENTAL STEEL	12 / 32 CONTINENTAL STEEL	
FRONT TIR	RES: 11R22.5	REAR TIR	<b>ES</b> : 11R22.5	

ADDITIONAL TIRE DETAIL	
FRONT TIRES ARE RALSM BRAND.	

GENERAL	OBSER	VATIONS
O LIVE I UVE	CECEIL	


OIL MILKY?	NO	LIGHTS WORK?	YES - ALL
OIL LEAKS?	SEE NOTES	WIPERS WORK?	YES
	110	0 1 1 0 E 0 1 1 0 E 1 1 0	VEC ALL

WATER LEAKS?	NO	GAUGES WORK?	YES - ALL	
OIL IN COOLANT?	NO	AIR HORN WORKS?	YES	
CLUTCH PLAY?	NA	CITY HORN WORKS?	YES	
STARTS?	YES			
DRIVES	YES	DIESEL PARTICULATE	FII TER	PASS

### ADDITIONAL OBSERVATIONS

CRACKED WINDSHIELD. TRIPAC APU DID NOT START.

WEAR & TEAR DETAIL		
DIAGNOSTICS	8 INACTIVE FAULTS DETECTED - (SEE ECM REPORT)	
INTERIOR CAB	TORN FABRIC ON DRIVERS SEAT. DAMAGED HANDLE ON DRAWER LATCH.	
DRIVER SIDE EXTERIOR	CHIPS/DINGS ON DRIVER SIDE EXTERIOR STORAGE DOOR. CHIPS/SCRATCHES ON EDGE OF DRIVER DOOR AND EXTERIOR LH MIRROR COVER.	
BUMPER	DAMAGED PLASTIC TRIM AT BOTTOM OF RH SIDE BUMPER.	
PASSENGER SIDE FENDER	DAMAGED FIBERGLASS FOR SIDE OF RH FENDER.	
CAB	LARGE DENT/DAMAGE ON PASSENGER SIDE EXTERIOR SLEEPER. LARGE SCRATCH ON BOTTOM OF PASSENGER SIDE DOOR.	
TIRES	1 TIRE BELOW 10/32	







### REPORT DOCUMENTS

Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services 101 W. Shrader St. Liberty, MO 64068 www.nationalinspect.com