



Commercial Credit Group, Inc (Mark Wenzel)
525 N Tryon Street, Charlotte, NC 28202 USA
(704) 414-2456

VIN: 3ALACWDT8GDHJ2302

2016 FREIGHTLINER M2 106

SPECIFICATIONS	
MILEAGE	442,093 / 442,139 (ECM)
ENGINE HOURS	13,998
ENGINE	CUMMINS ISB 6.7L 240 HP
ENG BRAKE	NO
ENG SERIAL	58568235
FUEL / TANKS	DIESEL - 2 ALUM 100 GAL TOTAL
TRANSMISSION	ALLISON 2500 RDS 6 SPD AUTO
DRIVE OPTS	POWER STEERING, OVERDRIVE, CRUISE
REAR END	DETROIT 5.13
AXLE TYPE	SINGLE - F 10,000 LB / R 17,500 LB
GVWR	26,000
FRAME	STEEL
SUSPENSION	AIR RIDE
WHEELBASE	255"
TIRE SIZE	295/75R22.5
WHEELS	F STEEL / R STEEL
REAR D TYPE	SWING
R DOOR (IN X IN)	78X40(2)
LIFT GATE MAKE	MAXON
LIFT GATE MODEL	GPTTLR
LIFT GATE CAPAC (LBS)	2500
INTERIOR H (IN)	97
EXTERIOR H (IN)	145
EXTERIOR W (IN)	96
EXTERIOR L (FT)	24.0
AIR COND	YES, OPERATIONAL
INTERIOR COLOR	GRAY
RADIO	AM/FM / CD, OPERATIONAL
MIRRORS	DUAL POWER
HIGH BACK SEATS	DUAL
PASSENGER SEAT	STATIONARY
EXTERIOR COLOR	YELLOW
BUMPER	PAINTED
EXTERIOR OPTS	HEATED MIRRORS
COLLISION AVOIDANCE?	NO



BRAKES	
LEFT FRONT	RIGHT FRONT
23	23
LEFT REAR 1	RIGHT REAR 1
23	23

TIRES & WHEELS			
LEFT FRONT		RIGHT FRONT	
20 / 32 STEEL		20 / 32 STEEL	
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
15 / 32 BRIDGESTONE STEEL	13 / 32 BRIDGESTONE STEEL	12 / 32 BRIDGESTONE STEEL	14 / 32 BRIDGESTONE STEEL
FRONT TIRES: 295/75R22.5		REAR TIRES: 295/75R22.5	

ADDITIONAL TIRE DETAIL
FRONT TIRES ARE JETWAY BRAND.

GENERAL OBSERVATIONS			
OIL MILKY?	NO	LIGHTS WORK?	YES - ALL
OIL LEAKS?	YES	WIPERS WORK?	YES

WATER LEAKS?	NO	GAUGES WORK?	YES - ALL
OIL IN COOLANT?	NO	AIR HORN WORKS?	NA
CLUTCH PLAY?	NA	CITY HORN WORKS?	YES
STARTS?	YES		
DRIVES	YES	DIESEL PARTICULATE FILTER	PASS

ADDITIONAL OBSERVATIONS

OIL COVERING BOTH LOWER SIDES OF ENGINE AND OIL PAN / NEEDS CLEANED TO IDENTIFY LEAKS

WEAR & TEAR DETAIL

DIAGNOSTICS	1 ACTIVE / 8 INACTIVE FAULTS - SEE REPORT
AXLES	OIL LEAKAGE FROM PINION SEAL ON REAR DRIVE AXLE
CAB	PAINT PEELING ON ROOF OF CAB
HOOD	PAINT CHIPS AROUND GRILLE / HEADLIGHTS
BUMPER	PAINT CHIPS
DOORS	LS HAS PAINT CHIPS / SCRATCHES - RS HAS PAINT CHIPS / SCRATCHES / RUSTED ALONG BOTTOM EDGE
CLEAN IDLE STICKER	PARTIALLY MISSING / PEELING
BOX EXTERIOR	LS HAS 5 PANELS BENT / DENTED / SEVERAL LIGHT SCRATCHES - RS HAS 1 PANEL DENTED / SEVERAL LIGHT SCRATCHES - RS FRONT RADIUS CRACKED NEAR BOTTOM EDGE - TOP REAR DRIP EDGE BENT - REAR DOCK PLATE BENT - TOP FRONT RADIUS HAS SEVERAL DENTS / SILICONE REPAIR
BOX INTERIOR	ROOF PANEL HAS SEPERATED FROM SUPPORT - WALLS SCRATCHED / SCUFFED
REAR DOORS	DOOR SEALS TORN
LIFT GATE	INOPERABLE / NO POWER TO SWITCHES
HEADLINER	STAINED
SEATS	LS BOTTOM WORN / STAINED
STEERING WHEEL	WORN AROUND THE EDGES
WINDSHIELD	CRACKED

REPORT PHOTOS







REPORT DOCUMENTS

Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services
101 W. Shrader St. Liberty, MO 64068
www.nationalinspect.com