



Commercial Credit Group, Inc (Mark Wenzel)
525 N Tryon Street, Charlotte, NC 28202 USA
(704) 414-2456

VIN: 3AKJGLDR7JSHR0746
PO #: 15030

2018 FREIGHTLINER CASCADIA 126

SPECIFICATIONS	
MILEAGE	505,520
ENGINE HOURS	22,647
ENGINE	DETROIT DD15 14.8L 450 HP
ENG BRAKE	YES
ENG SERIAL	472910S0473763
FUEL / TANKS	DIESEL - 2 ALUM 200 GAL TOTAL
EXHAUST	HORIZONTAL
TRANSMISSION	DETROIT DT12-OA-1550 HD 12 SPD AUTO
DRIVE OPTS	POWER STEERING, OVERDRIVE, CRUISE
REAR END	DETROIT 2.85
AXLE TYPE	TANDEM - F 12,350 LB / R 40,000 LB
GVWR	52,350
FRAME	STEEL
SUSPENSION	AIR RIDE
WHEELBASE	238"
TIRE SIZE	F 295/75R22.5 / R 275/80R22.5
WHEELS	F ALUMINUM / R ALUM/STEEL
WHEEL 5TH	AIR SLIDE
AIR COND	YES, OPERATIONAL
SLEEPER	72"
DUAL BUNK	YES
INTERIOR COLOR	GRAY
RADIO	AM/FM / CD
MIRRORS	DUAL POWER
HIGH BACK SEATS	DRIVER SIDE ONLY
EXTERIOR COLOR	WHITE
BUMPER	PLASTIC
EXTERIOR OPTS	HEATED MIRRORS, FULL FAIRINGS



BRAKES	
LEFT FRONT	RIGHT FRONT
23	24
LEFT REAR 1	RIGHT REAR 1
23	21
LEFT REAR 2	RIGHT REAR 2
23	23

TIRES & WHEELS			
LEFT FRONT		RIGHT FRONT	
18 / 32 ALUMINUM		10 / 32 ALUMINUM	
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
9 / 32 - ALUMINUM	10 / 32 - STEEL	2 / 32 - STEEL	10 / 32 - ALUMINUM
LEFT OUTER 2	LEFT INNER 2	RIGHT INNER 2	RIGHT OUTER 2
6 / 32 - ALUMINUM	12 / 32 - STEEL	10 / 32 - STEEL	2 / 32 - ALUMINUM
FRONT TIRES: 295/75R22.5		REAR TIRES: 275/80R22.5	

ADDITIONAL TIRE DETAIL
RANDOM TIRE BRANDS

GENERAL OBSERVATIONS

OIL MILKY?	NO	LIGHTS WORK?	YES - ALL
OIL LEAKS?	NO	WIPERS WORK?	YES
WATER LEAKS?	NO	GAUGES WORK?	YES - ALL
OIL IN COOLANT?	NO	AIR HORN WORKS?	YES
CLUTCH PLAY?	NA	CITY HORN WORKS?	YES

STARTS?	YES		
DRIVES	SEE NOTES	DIESEL PARTICULATE FILTER	PASS

ADDITIONAL OBSERVATIONS

IT WOULD NOT ENGAGE ANY GEAR FORWARD OR REVERSE.

WEAR & TEAR DETAIL

DIAGNOSTIC	REGEN AND HILL ASSIST LIGHT ARE ON. 1 ACTIVE FAULT / 1 INACTIVE FAULT FOUND - (SEE ECM REPORT)
HOOD	FENDER BOTH SIDES HAVE PAINT CHIPS AROUND HEADLIGHTS
CHASSIS, SUSPENSION AND AXLES.	REAR FRAME COMPONENTS SURFACE RUST
CATWALK	REAR DECK PLATES IS MISSING
SEATS	UPHOLSTERY STAINED AND WORN. PASSENGER SEAT IS MISSING
TIRES	4 TIRES WORN BELOW 10/32.

REPORT PHOTOS







REPORT DOCUMENTS

Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services
101 W. Shrader St. Liberty, MO 64068
www.nationalinspect.com