



**Commercial Credit Group, Inc (Mark Wenzel)**  
525 N Tryon Street, Charlotte, NC 28202 USA  
(704) 414-2456

VIN: 1XKYDP9X6HJ149636

**2017 KENWORTH T680**

SPECIFICATIONS	
MILEAGE	637,739
ENGINE HOURS	17,125
ENGINE	PACCAR MX13 455 HP
ENG BRAKE	YES
ENG SERIAL	Y110415
FUEL / TANKS	DIESEL - 2 ALUM 200 GAL TOTAL
EXHAUST	SINGLE
TRANSMISSION	EATON FAOM-15810C-EA3 10 SPD AUTO
DRIVE OPTS	POWER STEERING, OVERDRIVE, CRUISE
REAR END	MERITOR 2.64
AXLE TYPE	TANDEM - F 12,350 LB / R 40,000 LB
GVWR	52,350
FRAME	STEEL
SUSPENSION	AIR RIDE
WHEELBASE	227"
TIRE SIZE	295/75R22.5
WHEELS	F ALUMINUM / R ALUMINUM
WHEEL 5TH	AIR SLIDE
AIR COND	YES, OPERATIONAL
AUX POWER UNIT?	YES
SLEEPER	76"
DUAL BUNK	NO
INTERIOR COLOR	GREY
RADIO	AM/FM / CD, OPERATIONAL
MIRRORS	DUAL POWER
HIGH BACK SEATS	DUAL
PASSENGER SEAT	STATIONARY
EXTERIOR COLOR	WHITE
BUMPER	PLASTIC
EXTERIOR OPTS	HEATED MIRRORS, FULL FAIRINGS



BRAKES	
<b>LEFT REAR 1</b>	<b>RIGHT REAR 1</b>
20	22
<b>LEFT REAR 2</b>	<b>RIGHT REAR 2</b>
21	23

**ADDITIONAL BRAKE DETAIL**  
FRONT BRAKE LININGS WERE INACCESSIBLE FOR MEASUREMENT.

TIRES & WHEELS			
<b>LEFT FRONT</b>		<b>RIGHT FRONT</b>	
14 / 32 GOODYEAR ALUMINUM		12 / 32 GOODYEAR ALUMINUM	
<b>LEFT OUTER 1</b>	<b>LEFT INNER 1</b>	<b>RIGHT INNER 1</b>	<b>RIGHT OUTER 1</b>
12 / 32 CONTINENTAL ALUMINUM	12 / 32 CONTINENTAL ALUMINUM	16 / 32 BRIDGESTONE ALUMINUM	16 / 32 BRIDGESTONE ALUMINUM
<b>LEFT OUTER 2</b>	<b>LEFT INNER 2</b>	<b>RIGHT INNER 2</b>	<b>RIGHT OUTER 2</b>
14 / 32 DUNLOP ALUMINUM	13 / 32 CONTINENTAL ALUMINUM	6 / 32 GOODYEAR ALUMINUM	17 / 32 BRIDGESTONE ALUMINUM
<b>FRONT TIRES: 295/75R22.5</b>		<b>REAR TIRES: 295/75R22.5</b>	

**GENERAL OBSERVATIONS**

<b>OIL MILKY?</b>	NO	<b>LIGHTS WORK?</b>	YES - ALL
<b>OIL LEAKS?</b>	YES	<b>WIPERS WORK?</b>	YES
<b>WATER LEAKS?</b>	NO	<b>GAUGES WORK?</b>	YES - ALL
<b>OIL IN COOLANT?</b>	NO	<b>AIR HORN WORKS?</b>	YES
<b>CLUTCH PLAY?</b>	NA	<b>CITY HORN WORKS?</b>	YES

STARTS?	YES		
DRIVES	YES	DIESEL PARTICULATE FILTER	FAIL

**ADDITIONAL OBSERVATIONS**

BATTERIES NEEDED JUMP TO START. FAILED DUE TO ACTIVE AFTER TREATMENT FAULT. APU NEEDS SERVICE. CHIPS FOR CENTER WINDSHIELD. SEEPAGE AT BOTTOM OF OIL PAN / DRAIN PLUG.

WEAR & TEAR DETAIL	
DIAGNOSTICS	2 ACTIVE, 0 INACTIVE - SEE REPORT
DOOR	INTERIOR DOOR STOP IS MISSING FOR DRIVER SIDE.
TIRES	1 BELOW 10/32'S
PAINT	CHIPS, SCRATCHES AT VARIOUS AREAS. MISSING/PEELING PAINT FOR BOTH RH&LH MIRROR SUPPORTS.
SEAT	DAMAGED SEAT CUSHION FOR DRIVER SEAT
SLEEPER	MATTRESS MISSING

**REPORT PHOTOS**







Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services  
101 W. Shrader St. Liberty, MO 64068  
[www.nationalinspect.com](http://www.nationalinspect.com)