

National Inspection Services

Report: 272116 08/21/2024

VIN: 3AKJGEBG4HSJA7899

PO #: 15037

Commercial Credit Group, Inc (Mark Wenzel) 525 N Tryon Street, Charlotte, NC 28202 USA (704) 414-2456

2017 FREIGHTLINER CASCADIA 125 T/A

	SPECIFICATIONS
MILEAGE	447,306 / 447,308 (ECM)
ENGINE HOURS	13,641
ENGINE	CUMMINS ISX 400ST 400 HP
ENG BRAKE	YES
ENG SERIAL	79938147
FUEL / TANKS	DIESEL - 2 ALUM 200 GAL TOTAL
EXHAUST	SINGLE
TRANSMISSION	EATON-FULLER FRM-15210B 10 SPD MANUAL
DRIVE OPTS	POWER STEERING, CRUISE
REAR END	MERITOR 2.64
AXLE TYPE	TANDEM - F 12,000 LB / R 40,000 LB
GVWR	52,000
FRAME	STEEL
SUSPENSION	AIR RIDE
WHEELBASE	178"
TIRE SIZE	295/75/22.5
WHEELS	F ALUMINUM / R ALUMINUM
WHEEL 5TH	AIR SLIDE
AIR COND	YES, OPERATIONAL
INTERIOR COLOR	GREY
RADIO	AM/FM / CD, OPERATIONAL
MIRRORS	DUAL POWER
HIGH BACK SEATS	DUAL
PASSENGER SEAT	STATIONARY
EXTERIOR COLOR	WHITE
BUMPER	PLASTIC
EXTERIOR OPTS	HEATED MIRRORS, FULL FAIRINGS



BRAKES		
LEFT FRONT	RIGHT FRONT	
18	18	
LEFT REAR 1	RIGHT REAR 1	
13	12	
LEFT REAR 2	RIGHT REAR 2	
14	13	

TIRES & WHEELS			
LEFT FRONT 17/32 ALUMINUM		RIGHT FRONT 18 / 32 ALUMINUM	
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
17 / 32	17 / 32	16 / 32	16 / 32
ALUMINUM	ALUMINUM	ALUMINUM	ALUMINUM
LEFT OUTER 2	LEFT INNER 2	RIGHT INNER 2	RIGHT OUTER 2
16 / 32	16 / 32	16 / 32	10 / 32
-	-	-	-
ALUMINUM	ALUMINUM	ALUMINUM	ALUMINUM
FRONT TIRES: 295/75/22.5		REAR TIRES	3 : 295/75/22.5


		GENERAL OBSERVATIONS
OIL MILKY?	NO	LIGHTS WOR
OIL LEAKS?	NO	WIPERS WOR
WATER LEAKS?	NO	GAUGES WO
OIL IN COOLANT?	NO	AIR HORN W
CLUTCH PLAY?	ОК	CITY HORN W
STARTS?	YES	
DRIVES	YES	DIESEL BART
514120	120	DIESEL PART

LIGHTS WORK?	YES - ALL
WIPERS WORK?	YES
GAUGES WORK?	YES - ALL
AIR HORN WORKS?	YES
CITY HORN WORKS?	YES

DIESEL PARTICULATE FILTER	PASS

WEAR & TEAR DETAIL		
DIAGNOSTIC	CHECK ENGINE AND STOP ENGINE LIGHTS ARE ON. 1 ACTIVE FAULT / 19 INACTIVE FAULTS FOUND - (SEE ECM REPORT)	
DRIVER DOOR SEAL	TORN NEAR THE FLOOR AREA.	
HEADLIGHTS	RIGHT HEADLIGHT LENS BROKEN.	
HOOD	THE HOOD IS HEAVILY CRACKED ON THE RIGHT SIDE ABOVE THE HEADLIGHT.	
MIRRORS	LEFT MIRROR HOUSING COMPLETELY CRACKED.	





REPORT DOCUMENTS

Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services 101 W. Shrader St. Liberty, MO 64068 www.nationalinspect.com