



Commercial Credit Group, Inc (Mark Wenzel)
525 N Tryon Street, Charlotte, NC 28202 USA
(704) 414-2456

VIN: 1HTMMMML4KH514846
PO #: 15045

2019 INTERNATIONAL 4300

SPECIFICATIONS	
MILEAGE	250,356 / 250,356 (ECM)
ENGINE HOURS	6,222
ENGINE	CUMMINS B6.7L 220 HP
ENG SERIAL	74294668
FUEL / TANKS	DIESEL - 1 ALUM 70 GAL TOTAL
TRANSMISSION	EATON-FULLER EDCO-6F107A 7 SPD AUTO
DRIVE OPTS	POWER STEERING, OVERDRIVE, CRUISE
REAR END	MERITOR 5.29
AXLE TYPE	SINGLE - F 10,000 LB / R 17,500 LB
GVWR	27,500
FRAME	STEEL
SUSPENSION	AIR RIDE
WHEELBASE	272"
TIRE SIZE	F 11R22.5 / R 11R 22.5
WHEELS	F STEEL / R STEEL
REAR D TYPE	ROLL-UP
R DOOR (IN X IN)	97X90
LIFT GATE MAKE	DHOLLANDIA
LIFT GATE CAPAC (LBS)	3300
EXTERIOR W (IN)	102
EXTERIOR L (FT)	26.5
AIR COND	YES
INTERIOR COLOR	GRAY
RADIO	AM/FM, OPERATIONAL
HIGH BACK SEATS	DUAL
PASSENGER SEAT	STATIONARY
EXTERIOR COLOR	YELLOW
BUMPER	PAINTED



BRAKES	
LEFT FRONT	RIGHT FRONT
COVERED	COVERED
LEFT REAR 1	RIGHT REAR 1
COVERED	COVERED

ADDITIONAL BRAKE DETAIL
ALL BRAKES SHIELDED

TIRES & WHEELS			
LEFT FRONT		RIGHT FRONT	
9 / 32 STEEL		14 / 32 STEEL	
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
6 / 32 - STEEL	5 / 32 - STEEL	17 / 32 - STEEL	12 / 32 - STEEL
FRONT TIRES: 11R22.5		REAR TIRES: 11R 22.5	

ADDITIONAL TIRE DETAIL
RANDOM TIRE BRANDS

GENERAL OBSERVATIONS

OIL MILKY?	NO	LIGHTS WORK?	YES - ALL
OIL LEAKS?	NO	WIPERS WORK?	YES
WATER LEAKS?	NO	GAUGES WORK?	YES - ALL
OIL IN COOLANT?	NO	AIR HORN WORKS?	YES
CLUTCH PLAY?	NA	CITY HORN WORKS?	YES
STARTS?	YES		
DRIVES	YES	DIESEL PARTICULATE FILTER	FAIL

ADDITIONAL OBSERVATIONS

DPF FAIL: SPN 3031 FMI 9- CATALYST TANK TEMPERATURE ABNORMAL UPDATE RATE. SPN 3251 FMI 0- AFT 1 DPF DIFFERENTIAL PRESSURE DATA VALID BUT ABOVE NORMAL OPERATIONAL RANGE. SPN 3720 FMI 15- AFT 1 DPF ASH LOAD PERCENT DATA VALID BUT ABOVE NORMAL OPERATING RANGE.

WEAR & TEAR DETAIL

DIAGNOSTIC	CHECK ENGINE AND MIL LIGHTS ARE ON. 3 ACTIVE FAULTS / 5 INACTIVE FAULTS FOUND - (SEE ECM REPORT)
HOOD	FENDER BOTH SIDES HAS PAINT CHIPS AROUND HEADLIGHTS AND RS DAMAGE
VAN BOX SIDE PANELS	BOX PANELS BOTH SIDES HAVE SLIGHT ABRASIONS AND REAR DOOR FRAME RS PAINT FLAKING FROM BASE TO TOP
BOX PANELS	RS LOWER PANELS SCOURED W/ VERTICAL SEAM OPENED UP
DOORS	PASSENGER DOOR SCUFFED
SEATS	UPHOLSTERY STAINED AND WORN.
INTERIOR BOX	WATER LEAKING AT BOTH ROOF NOSING AREAS
TIRES	3 TIRES, WORN BELOW 10/32.

REPORT PHOTOS









REPORT DOCUMENTS

Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services
101 W. Shrader St. Liberty, MO 64068
www.nationalinspect.com