



Commercial Credit Group, Inc (Mark Wenzel)
525 N Tryon Street, Charlotte, NC 28202 USA
(704) 414-2456

VIN: 3HSDZAPR5JN249640

2018 INTERNATIONAL LT625

SPECIFICATIONS	
MILEAGE	563,683 / 563,749 (ECM)
ENGINE HOURS	15,410
ENGINE	CUMMINS X15 14.9L 400 HP
ENG BRAKE	YES
ENG SERIAL	80012925
FUEL / TANKS	DIESEL - 2 ALUM 200 GAL TOTAL
EXHAUST	HORIZONTAL
TRANSMISSION	EATON FAOM-15810S-EC3 10 SPD AUTO
DRIVE OPTS	POWER STEERING, OVERDRIVE, CRUISE
REAR END	MERITOR 2.64
AXLE TYPE	TANDEM - F 12,350 LB / R 40,000 LB
GVWR	52,350
FRAME	STEEL
SUSPENSION	AIR RIDE
WHEELBASE	221"
TIRE SIZE	295/75R22.5
WHEELS	F ALUMINUM / R ALUMINUM
WHEEL 5TH	AIR SLIDE
AIR COND	YES
SLEEPER	56"
DUAL BUNK	NO
INTERIOR COLOR	GRAY
RADIO	AM/FM / CD, OPERATIONAL
MIRRORS	DUAL POWER
HIGH BACK SEATS	DUAL
PASSENGER SEAT	STATIONARY
EXTERIOR COLOR	WHITE
BUMPER	PLASTIC
EXTERIOR OPTS	HEATED MIRRORS, FULL FAIRINGS
COLLISION AVOIDANCE?	YES



BRAKES	
LEFT FRONT	RIGHT FRONT
21	19
LEFT REAR 1	RIGHT REAR 1
7	7
LEFT REAR 2	RIGHT REAR 2
7	6

TIRES & WHEELS			
LEFT FRONT		RIGHT FRONT	
9 / 32 GOODYEAR ALUMINUM		9 / 32 GOODYEAR ALUMINUM	
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
16 / 32 GOODYEAR ALUMINUM	19 / 32 GOODYEAR ALUMINUM	18 / 32 GOODYEAR ALUMINUM	18 / 32 GOODYEAR ALUMINUM
LEFT OUTER 2	LEFT INNER 2	RIGHT INNER 2	RIGHT OUTER 2
15 / 32 GOODYEAR ALUMINUM	15 / 32 GOODYEAR ALUMINUM	15 / 32 GOODYEAR ALUMINUM	16 / 32 GOODYEAR ALUMINUM
FRONT TIRES: 295/75R22.5		REAR TIRES: 295/75R22.5	

GENERAL OBSERVATIONS

OIL MILKY?	NO	LIGHTS WORK?	SEE NOTES
OIL LEAKS?	YES	WIPERS WORK?	YES
WATER LEAKS?	NO	GAUGES WORK?	SEE NOTES
OIL IN COOLANT?	NO	AIR HORN WORKS?	SEE NOTES
CLUTCH PLAY?	NA	CITY HORN WORKS?	YES

STARTS?	SEE NOTES
DRIVES	SEE NOTES

ADDITIONAL OBSERVATIONS

UNIT TOWED TO LOCATION. BATTERIES WEAK. LIMITED ELECTRICAL OPERATION. UNABLE TO START ENGINE OR TEST ALL SYSTEMS. OIL LEAKAGE ALONG OIL PAN GASKET.

WEAR & TEAR DETAIL

DIAGNOSTICS	4 ACTIVE / 15 INACTIVE FAULTS DETECTED (SEE ECM REPORT)
BUMPER	RIGHT SIDE SCRATCHED, LEFT SIDE SCRAPED / GOUGED
ROOF	PAINT PEELING
HOOD / FENDERS	LARGE SCRATCH ON LEFT SIDE, PAINT CHIPS AT FRONT
TANK FAIRING	LEFT SIDE SCRAPED
ANTENNA	MISSING AT LEFT SIDE OF CAB
LIGHTS	LOW HEADLIGHT BEAM AND MARKER LIGHT INOP
DOOR MIRROR	RIGHT SIDE HOUSING CRACKED
INTERIOR	SURFACES AND UPHOLSTERY ARE DIRTY
POWER STEERING	RESERVOIR HOSE LEAKING
WINDSHIELD	GLASS CHIPPED
SEATS	UPHOLSTERY WORN / STAINED
BRAKES	LININGS WORN THIN AT REAR AXLES

REPORT PHOTOS







REPORT DOCUMENTS

Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services
101 W. Shradar St. Liberty, MO 64068
www.nationalinspect.com