



**Commercial Credit Group, Inc (Mark Wenzel)**  
525 N Tryon Street, Charlotte, NC 28202 USA  
(704) 414-2456

VIN: 3AKJGED50GDHJ3206

**2016 FREIGHTLINER CASCADIA 125**

SPECIFICATIONS	
ENGINE	DETROIT DD15 14.8L 455 HP
ENG BRAKE	YES
FUEL / TANKS	DIESEL - 2 STEEL 160 GAL TOTAL
EXHAUST	HORIZONTAL
TRANSMISSION	DETROIT DT12-DA-1750 HD 12 SPD AUTO
DRIVE OPTS	POWER STEERING, CRUISE
REAR END	DETROIT 2.53
AXLE TYPE	TANDEM - F 12,000 LB / R 40,000 LB
GVWR	52,000
FRAME	STEEL
SUSPENSION	AIR RIDE
WHEELBASE	178"
TIRE SIZE	11R22.5
WHEELS	F ALUMINUM / R ALUMINUM
WHEEL 5TH	AIR SLIDE
AIR COND	YES
INTERIOR COLOR	GREY
RADIO	AM/FM
MIRRORS	DUAL POWER
HIGH BACK SEATS	DUAL
PASSENGER SEAT	STATIONARY
EXTERIOR COLOR	RED
BUMPER	CHROME
EXTERIOR OPTS	HEATED MIRRORS, CAB / ROOF FAIRINGS



BRAKES	
<b>LEFT FRONT</b>	<b>RIGHT FRONT</b>
COVERED	COVERED
<b>LEFT REAR 1</b>	<b>RIGHT REAR 1</b>
COVERED	COVERED
<b>LEFT REAR 2</b>	<b>RIGHT REAR 2</b>
COVERED	COVERED

TIRES & WHEELS			
<b>LEFT FRONT</b>		<b>RIGHT FRONT</b>	
13 / 32 BRIDGESTONE ALUMINUM		14 / 32 BRIDGESTONE ALUMINUM	
<b>LEFT OUTER 1</b>	<b>LEFT INNER 1</b>	<b>RIGHT INNER 1</b>	<b>RIGHT OUTER 1</b>
2 / 32 BRIDGESTONE ALUMINUM	6 / 32 BRIDGESTONE ALUMINUM	7 / 32 CONTINENTAL ALUMINUM	3 / 32 CONTINENTAL ALUMINUM
<b>LEFT OUTER 2</b>	<b>LEFT INNER 2</b>	<b>RIGHT INNER 2</b>	<b>RIGHT OUTER 2</b>
19 / 32 MICHELIN ALUMINUM	19 / 32 MICHELIN ALUMINUM	2 / 32 MICHELIN ALUMINUM	5 / 32 MICHELIN ALUMINUM
<b>FRONT TIRES: 11R22.5</b>		<b>REAR TIRES: 11R22.5</b>	

**GENERAL OBSERVATIONS**

<b>OIL MILKY?</b>	NO	<b>LIGHTS WORK?</b>	SEE NOTES
<b>OIL LEAKS?</b>	YES	<b>WIPERS WORK?</b>	SEE NOTES
<b>WATER LEAKS?</b>	NO	<b>GAUGES WORK?</b>	SEE NOTES
<b>OIL IN COOLANT?</b>	NO	<b>AIR HORN WORKS?</b>	SEE NOTES
<b>CLUTCH PLAY?</b>	NA	<b>CITY HORN WORKS?</b>	SEE NOTES
<b>STARTS?</b>	SEE NOTES		
<b>DRIVES</b>	SEE NOTES		

**ADDITIONAL OBSERVATIONS**

ENGINE OIL LEAK AT THE REAR OF THE OIL PAN

**WEAR & TEAR DETAIL**

<b>DIAGNOSTICS</b>	NO KEY COULD NOT RUN OR ALL CHECK FUNCTIONS
<b>MIRROR</b>	SIDE MIRROR SCRATCHED ON DRIVER SIDE
<b>DOOR</b>	WINDOW BUTTON MISSING FROM DRIVER DOOR. SCRAPED ON THE P/S
<b>COWL</b>	CHIPPED ON P/S
<b>CAB</b>	REAR OF CAB SCUFFED FROM AIR HOSES AND PAINT IS PEELING ON D/S. RUST STAINING ON REAR OF CAB
<b>STEERING WHEEL</b>	SURFACES HAVE WEAR
<b>DASH</b>	ADHESIVE RESIDUE IN THE CENTER OF THE DASH
<b>FUEL TANKS</b>	STRAP MISSING ON D/S
<b>SEATS</b>	BOTH ARE SHOWING WEAR
<b>TIRES</b>	5 TIRES BELOW 10/32.

**REPORT PHOTOS**





Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services  
101 W. Shrader St. Liberty, MO 64068  
[www.nationalinspect.com](http://www.nationalinspect.com)