

National Inspection Services

Report: 269528 07/19/2024

Commercial Credit Group, Inc (Mark Wenzel) 525 N Tryon Street, Charlotte, NC 28202 USA (704) 414-2456 VIN: 1VRL07059L1003530

2020 VERMEER S925TX-9D 9

	SPECIFICATIONS
ENGINE	KUBOTA
FUEL / TANKS	DIESEL
TIRE SIZE	TRACK



NOTES / DESCRIPTION


DOESN'T RUN

BRAKES		TIRES & WHEELS			
LEFT REAR 1	RIGHT REAR 1	LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
		EPONT TIE	RES: TRACK	PEAR TIE	RES: TRACK

GENERAL OBSERVATIONS					
OIL MILKY?	NO	LIGHTS WORK?	NA		
OIL LEAKS?	NO	WIPERS WORK?	NA		
WATER LEAKS?	NO	GAUGES WORK?	NA		
OIL IN COOLANT?	NO	AIR HORN WORKS?	NA		
CLUTCH PLAY?	NA	CITY HORN WORKS?	NA		
STARTS?	NO				
DRIVES	NO				

WEAR & TEAR DETAIL		
DIAGNOSTICS	NO POWER COULD NOT RUN OR CHECK ALL FUNCTIONS	
COVERS	ENGINE COVERS ARE REMOVED	
ATTACHMENT	RUSTED IN MULTIPLE SPOTS	





Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services 101 W. Shrader St. Liberty, MO 64068 www.nationalinspect.com