



Commercial Credit Group, Inc (Mark Wenzel)
525 N Tryon Street, Charlotte, NC 28202 USA
(704) 414-2456

VIN: 3AKJGEDVXFDGL1501
PO #: 12870

2015 FREIGHTLINER CASCADIA 125

SPECIFICATIONS	
ENGINE	DETROIT DD13 12.8L 435 HP
ENG BRAKE	YES
ENG SERIAL	471927S0267326
FUEL / TANKS	DIESEL - 2 ALUM 180 GAL TOTAL
EXHAUST	SINGLE
TRANSMISSION	EATON-FULLER FO16E313A-MHP 13 SPD AUTO
DRIVE OPTS	POWER STEERING, CRUISE
REAR END	MERITOR 3.55
AXLE TYPE	TANDEM - F 12,000 LB / R 40,000 LB
GVWR	52,000
FRAME	STEEL
SUSPENSION	AIR RIDE
WHEELBASE	178"
TIRE SIZE	11R22.5
WHEELS	F STEEL / R STEEL
WHEEL 5TH	AIR SLIDE
AIR COND	YES
AUX POWER UNIT?	NO
INTERIOR COLOR	GRAY TAN
RADIO	AM/FM / CD
MIRRORS	DUAL POWER
HIGH BACK SEATS	DUAL
PASSENGER SEAT	STATIONARY
EXTERIOR COLOR	WHITE
EXTERIOR OPTS	HEATED MIRRORS, CAB / ROOF FAIRINGS



BRAKES	
LEFT FRONT	RIGHT FRONT
COVERED	COVERED
LEFT REAR 1	RIGHT REAR 1
COVERED	COVERED
LEFT REAR 2	RIGHT REAR 2
COVERED	COVERED

TIRES & WHEELS			
LEFT FRONT		RIGHT FRONT	
7 / 32 STEEL		7 / 32 YOKOHAMA STEEL	
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
10 / 32 - STEEL	5 / 32 - STEEL	7 / 32 - STEEL	8 / 32 - STEEL
LEFT OUTER 2	LEFT INNER 2	RIGHT INNER 2	RIGHT OUTER 2
12 / 32 MICHELIN STEEL	- - -	12 / 32 - STEEL	9 / 32 - STEEL
FRONT TIRES: 11R22.5		REAR TIRES: 11R22.5	

GENERAL OBSERVATIONS

OIL MILKY?	NO	LIGHTS WORK?	NA
OIL LEAKS?	NO	WIPERS WORK?	NO
WATER LEAKS?	NO	GAUGES WORK?	NA
OIL IN COOLANT?	NO	AIR HORN WORKS?	NO
CLUTCH PLAY?	NA	CITY HORN WORKS?	NO
STARTS?	NO		
DRIVES	NO		

WEAR & TEAR DETAIL

DIAGNOSTICS	BATTERY DEAD. UNABLE TO JUMP START BECAUSE OF VARIOUS ENGINE COMPONENTS MISSING
--------------------	---

TURBO	TURBO DISCONNECTED AND SPLIT IN HALF BROKEN
ENGINE	VARIOUS ENGINE COMPONENTS MISSING OR BROKEN
BUMPER	FRONT BUMPER ASSEMBLY MISSING
TIRES	6 TIRES LESS THAN 10/32 TIRES ARE ALL BAD AND WORN. MISSING A3 LEFT SIDE INSIDE TIRE.
MUD FLAPS	MISSING BOTH REAR MUDFLAPS AND DRIVER SIDE QUARTER FENDER
AIRBAG	LEFT REAR REAR AIR BAG NOT SITTING ON TOP MOUNT PROPERLY
CHASSIS	RUST ON FRAME RAILS, CROSSMEMBERS AND AXLES
STEERING WHEEL	SURFACES HAVE WEAR
DASH	INSTRUMENT CLUSTER LENS DAMAGED.
SEATS	BOTH ARE STAINED AND WORN

REPORT PHOTOS





Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services
 101 W. Shrader St. Liberty, MO 64068
www.nationalinspect.com