



Commercial Credit Group, Inc (Mark Wenzel)
525 N Tryon Street, Charlotte, NC 28202 USA
(704) 414-2456

VIN: 3AKJGLD55GSHS0202
PO #: 14446

2016 FREIGHTLINER CASCADIA 125

| SPECIFICATIONS | |
|-----------------|-------------------------------------|
| ENGINE | DETROIT DD15 14.8L 455 HP |
| ENG BRAKE | YES |
| ENG SERIAL | 492906S0382912 |
| FUEL / TANKS | DIESEL - 2 ALUM 220 GAL TOTAL |
| EXHAUST | HORIZONTAL |
| TRANSMISSION | DETROIT DT12-OA-1750 HD 12 SPD AUTO |
| DRIVE OPTS | POWER STEERING, OVERDRIVE, CRUISE |
| REAR END | DETROIT 3.08 |
| AXLE TYPE | TANDEM - F 13,220 LB / R 40,000 LB |
| GVWR | 53,220 |
| FRAME | STEEL |
| SUSPENSION | AIR RIDE |
| WHEELBASE | 228" |
| TIRE SIZE | 11R22.5 |
| WHEELS | F ALUMINUM / R ALUMINUM |
| WHEEL 5TH | AIR SLIDE |
| AIR COND | YES |
| AUX POWER UNIT? | YES |
| SLEEPER | 73" |
| DUAL BUNK | YES |
| INTERIOR COLOR | GRAY / TAN |
| RADIO | AM/FM / CD |
| MIRRORS | DUAL POWER |
| HIGH BACK SEATS | DUAL |
| PASSENGER SEAT | AIR RIDE |
| EXTERIOR COLOR | WHITE |
| BUMPER | CHROME |
| EXTERIOR OPTS | HEATED MIRRORS |



| BRAKES | |
|--------------------|---------------------|
| LEFT FRONT | RIGHT FRONT |
| 13 | 12 |
| LEFT REAR 1 | RIGHT REAR 1 |
| 26 | 26 |
| LEFT REAR 2 | RIGHT REAR 2 |
| 26 | 26 |

| TIRES & WHEELS | | | |
|------------------------------------|------------------------------------|------------------------------------|------------------------------------|
| LEFT FRONT | | RIGHT FRONT | |
| 13 / 32 BRIDGESTONE ALUMINUM | | 12 / 32 BRIDGESTONE ALUMINUM | |
| LEFT OUTER 1 | LEFT INNER 1 | RIGHT INNER 1 | RIGHT OUTER 1 |
| 6 / 32 CONTINENTAL ALUMINUM | 6 / 32 CONTINENTAL ALUMINUM | 7 / 32 BRIDGESTONE ALUMINUM | 7 / 32 BRIDGESTONE ALUMINUM |
| LEFT OUTER 2 | LEFT INNER 2 | RIGHT INNER 2 | RIGHT OUTER 2 |
| 19 / 32 BRIDGESTONE ALUMINUM | 17 / 32 BRIDGESTONE ALUMINUM | 17 / 32 BRIDGESTONE ALUMINUM | 17 / 32 BRIDGESTONE ALUMINUM |
| FRONT TIRES: 11R22.5 | | REAR TIRES: 11R22.5 | |

GENERAL OBSERVATIONS

| | | | |
|------------------------|-----------|-------------------------|-----------|
| OIL MILKY? | NO | LIGHTS WORK? | SEE NOTES |
| OIL LEAKS? | SEE NOTES | WIPERS WORK? | SEE NOTES |
| WATER LEAKS? | NO | GAUGES WORK? | SEE NOTES |
| OIL IN COOLANT? | NO | AIR HORN WORKS? | SEE NOTES |
| CLUTCH PLAY? | NA | CITY HORN WORKS? | SEE NOTES |
| STARTS? | NO | | |
| DRIVES | SEE NOTES | | |

ADDITIONAL OBSERVATIONS

SITE CONTACT STATES TRUCK IS IN NON RUNNING CONDITION, BATTERIES ARE ALSO DEAD, UNABLE TO TEST COMPONENTS, OR OBTAIN DATA / REPORT - OIL RESIDUE / SEEPAGE AROUND OIL PAN SEAL - SEEPAGE AROUND INJECTOR TUBES / LINES

WEAR & TEAR DETAIL

| | |
|------------------------|---|
| TIRES | FOUR TIRES BELOW 10/32 |
| CAB | PAINT CHIPS / SCRATCHES / RUST STAINS / SILICONE REPAIR HOLES ON BACK OF CAB - LS STORAGE DOOR EDGES BENT |
| HOOD | PAINT CHIPS AROUND GRILLE / HEADLIGHTS - RS SCRATCHED BELOW HEADLIGHT FROM BUMPER VALANCE RUBBING |
| BUMPER | SEVERELY BENT - RS UPPER VALANCE UPPER EDGE PAINT RUBBED OFF FROM RUBBING ON HOOD |
| DOORS | LS DOOR SEAL TORN |
| QUARTER FENDERS | LS BROKEN |
| RUST | LIGHT RUST ON SEVERAL COMPONENTS ON CHASSIS |
| STEERING WHEEL | WORN AROUND THE EDGES |
| SEATS | LS BOTTOM WORN / STAINED / BACK WORN / STAINED - RS BOTTOM STAINED |
| BUNK | LOWER MATTRESS MISSING |

REPORT PHOTOS







Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services
101 W. Shrader St. Liberty, MO 64068
www.nationalinspect.com