



**Commercial Credit Group, Inc (Mark Wenzel)**  
525 N Tryon Street, Charlotte, NC 28202 USA  
(704) 414-2456

VIN: 1UYVS2539FM115407

**2015 UTILITY VS2RA**

SPECIFICATIONS	
AXLE TYPE	TANDEM - F 20,000 LB / R 20,000 LB
SPREAD AXLE	NO
FRAME	STEEL
SUSPENSION	AIR RIDE
TIRE SIZE	275/80R22.5
WHEELS	F ALUMINUM / R ALUMINUM
REEFER TYPE	DIESEL
REEFER MAKE	THERMOKING
REEFER MODEL	SR4
REAR D TYPE	SWING
EXTERIOR L (FT)	53.0
EXTERIOR COLOR	WHITE



BRAKES	
<b>LEFT REAR 1</b>	<b>RIGHT REAR 1</b>
22	22
<b>LEFT REAR 2</b>	<b>RIGHT REAR 2</b>
22	22


TIRES & WHEELS			
<b>LEFT OUTER 1</b>	<b>LEFT INNER 1</b>	<b>RIGHT INNER 1</b>	<b>RIGHT OUTER 1</b>
8 / 32 MICHELIN ALUMINUM	7 / 32 UNIROYAL ALUMINUM	7 / 32 BRIDGESTONE ALUMINUM	7 / 32 BRIDGESTONE ALUMINUM
<b>LEFT OUTER 2</b>	<b>LEFT INNER 2</b>	<b>RIGHT INNER 2</b>	<b>RIGHT OUTER 2</b>
2 / 32 GOODYEAR ALUMINUM	4 / 32 DUNLOP ALUMINUM	8 / 32 GOODYEAR ALUMINUM	7 / 32 CONTINENTAL ALUMINUM
<b>FRONT TIRES: 275/80R22.5</b>		<b>REAR TIRES: 275/80R22.5</b>	

**ADDITIONAL OBSERVATIONS**  
REEFER WOULDN'T START. WEEDS AND TREES COVERED THE REAR DOORS.

WEAR & TEAR DETAIL	
<b>TIRES</b>	8 TIRES LESS THAN 10/32
<b>EXTERIOR BOX</b>	SCRATCHES DOWN BOTH SIDES. D/S BOTTOM RAIL IS BENT TOWARDS THE REAR. P/S REAR CORNER IS BENT.
<b>MUD FLAP</b>	MUD FLAP HANGER BENT.
<b>FAIRING</b>	D/S LOWER FAIRING IS LOOSE, HAS BEEN REMOUNTED.

**REPORT PHOTOS**





Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services  
 101 W. Shrader St. Liberty, MO 64068  
[www.nationalinspect.com](http://www.nationalinspect.com)