Southern AG Logistics & Recovery <u>Fayetteville, NC</u>

2017 FREIGHTLINER CASCADIA 125



Asset Detail		
VIN	3AKJGLD56GSHA6899	
STOCK#	NA	
LOT#	6899	
PO#	NA	
YEAR	2017	
MAKE	FREIGHTLINER	
MODEL	Cascadia 125	
TYPE	Truck ()	

Asset Specifications			
OD MILES	658527	ENG MAKE	Detroit
ENG DETAIL	DD15	ENG HP	450
ENG BRAKE	Yes	FUEL TYPE	Diesel
FUEL TANKS	2	FUEL CAPAC	240
TRANS MAKE	Detroit	TRANS MODEL	DT112
TRANS SPD.	12	TRANS TYPE	Auto
OVER DRIVE	Yes	CRUISE	Yes
PWR STEER	Yes	REAR SPEC	Detroit
REAR RATIO	3.08	AXLE TYPE	Tandem
AXLE F	12000	AXLE R	20000
GVW	52000	SUSPENSION	Shock / Spring
WHEELBASE	228	TIRE SIZE R	295/75R22.5
TIRE SIZE F	295/75R22.5	WHEEL F	Steel
WHEEL R	Steel	AIR COND	Yes
AIR COND OPERABLE	No	INT COLOR	Black
RADIO	AM/FM/CD	RADIO OPERABLE	No
POWER MIRRORS	LH Power Only	HIGH BACK SEATS	Driver Side Only
PASS SEAT	Stationary	EXT COLOR	White
BUMPER	Plastic	HEATED MIR	Yes
VISOR	Yes		

INSPECTION REPORT

Report #34506 07/18/2024

COMMERCIAL CREDIT GROUP, INC

Southern AG Logistics & Recovery <u>Fayetteville, NC</u>

Bra	kes
/ 32	/ 32 FR

Tires & Wheels			
FL	15 / 32 Kelly Steel	15 / 32 Kelly Steel	FR

	BRAKE 1	TYPE: NA	
/ 3	2	/ 32	RR 1
RL 2 / 3	2	/ 32	RR 2

FRONT: 295/75R22.5		REAR: 29	5/75R22 . 5
RLo1 6/32	RLi1 5 / 32	2 / 32 RRi1	1 / 32 RRo1
Goodyear	Federal	BF Goodrich	Dunlap
Steel	Steel	Steel	Steel
RLo2 5 / 32	RLi2 4 / 32	6 / 32 RRi2	4 / 32 RRo2
Goodyear	Firestone	Bridgestone	Goodyear
Steel	Steel	Steel	Steel

General Observations

Oil Leaks: No Oil Milky: No Water Leaks: No Oil in Coolant: No Starts: No Runs/Drives: No

Safety Observations

Exterior Lights Operable: **See Detail** Wipers Operable: **See Detail** Guages Operable: **See Detail** City Horn Operable: **See Detail** Air Horn Operable: **See Detail**

INSPECTION REPORT

Report #34506 07/18/2024

COMMERCIAL CREDIT GROUP, INC

Southern AG Logistics & Recovery <u>Fayetteville, NC</u>

Wear & Tear Observations		
No crank	Batteries dead. Was able to get dash to work with jump box	
Manufacturing date	Truck is showing manufacture date as 2/25	
Tires	Various manufacturers on the rear. Most of which need replacement. Front in good shape	
Interior	Good. Needs cleaning	

COMMERCIAL CREDIT GROUP, INC

Southern AG Logistics & Recovery <u>Fayetteville, NC</u>







