

National Inspection Services

Report: 272123 08/16/2024

VIN: 3AKJGLBG8GSHT3126

PO #: 14659

Commercial Credit Group, Inc (Mark Wenzel) 525 N Tryon Street, Charlotte, NC 28202 USA (704) 414-2456

2016 FREIGHTLINER CASCADIA

GENERAL OBSERVATIONS

	SPECIFICATIONS
MILEAGE	606,930 / 606,930 (ECM)
ENGINE HOURS	25,626
ENGINE	CUMMINS 450 HP
FUEL / TANKS	DIESEL - 2 ALUM 240 GAL TOTAL
EXHAUST	SINGLE
EXTERNAL BREATHERS	SINGLE
TRANSMISSION	EATON-FULLER FO16-E AUTO
DRIVE OPTS	POWER STEERING, CRUISE
REAR END	MERITOR 3.36
AXLE TYPE	TANDEM - F 12 LB / R 20,000 LB
GVWR	52,000
FRAME	STEEL
SUSPENSION	AIR / SPRING
TIRE SIZE	295 75 22.5
WHEELS	F SPOKE / R STEEL
WHEEL 5TH	AIR SLIDE
AIR COND	YES, OPERATIONAL
SLEEPER	86W X 96"H X 60"D"
DUAL BUNK	YES
INTERIOR COLOR	GRAY
RADIO	AM/FM / BLUE, OPERATIONAL
MIRRORS	DUAL POWER
HIGH BACK SEATS	DUAL
PASSENGER SEAT	AIR RIDE
EXTERIOR COLOR	WHITE
BUMPER	CHROME
EXTERIOR OPTS	HEATED MIRRORS, FULL FAIRINGS
COLLISION AVOIDANCE?	YES



BRAKES			
LEFT FRONT	RIGHT FRONT		
14	14		
LEFT REAR 1	RIGHT REAR 1		
12	12		
LEFT REAR 2	RIGHT REAR 2		
18	16		
ADDITIONAL BRAKE DETAIL			

DRUM F&R

LEFT FRONT		RIGHT FRONT	
11 / 32 GENERAL		13 / 32 GOODYEAR	
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
9 / 32 BRIDGESTONE -	7 / 32 BRIDGESTONE -	9 / 32 BRIDGESTONE -	10 / 32 BRIDGESTONE -
LEFT OUTER 2	LEFT INNER 2	RIGHT INNER 2	RIGHT OUTER 2
9 / 32 BRIDGESTONE -	7 / 32 BRIDGESTONE -	7/32 BRIDGESTONE -	7 / 32 BRIDGESTONE -
FRONT TIRES	S : 295 75 22.5	REAR TIRES	3 : 295 75 22.5

TIRES & WHEELS

OIL MILKY?	NO
OIL LEAKS?	YES
WATER LEAKS?	NO
OIL IN COOLANT?	NO
CLUTCH PLAY?	NA
STARTS?	YES
DRIVES	YES

LIGHTS WORK?	YES - ALL
WIPERS WORK?	YES
GAUGES WORK?	YES - ALL
AIR HORN WORKS?	YES
CITY HORN WORKS?	YES

DIESEL PARTICULATE FILTER	PASS
---------------------------	------

ADDITIONAL OBSERVATIONS

OIL LEAKS FROM THE REAR ENGINE SEAL AND THE OIL PAN.

WEAR & TEAR DETAIL

DIAGNOSTICS 1 ACTIVE FAULT / 18 INACTIVE FAULTS FOUND - (SEE ECM REPORT)

HOOD STRUTSWORN, NEED REPLACEMENTTIRES7 TIRES WORN BELOW 10/32.

REPORT PHOTOS 6 E



REPORT DOCUMENTS

Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services 101 W. Shrader St. Liberty, MO 64068 www.nationalinspect.com