

National Inspection Services

Report: 271712 08/15/2024

VIN: 3ALACWDT0HDHV3072

PO #: 15108

Commercial Credit Group, Inc (Mark Wenzel) 525 N Tryon Street, Charlotte, NC 28202 USA (704) 414-2456

2017 FREIGHTLINER M2 106

	SPECIFICATIONS
MILEAGE	290,873
ENGINE HOURS	8,815
ENGINE	CUMMINS ISB 6.7L 220 HP
ENG SERIAL	58639856
FUEL / TANKS	DIESEL - 1 ALUM 80 GAL TOTAL
TRANSMISSION	ALLISON 2200 RDS 6 SPD AUTO
DRIVE OPTS	POWER STEERING, OVERDRIVE, CRUISE
REAR END	DETROIT 5.56
AXLE TYPE	SINGLE - F 10,000 LB / R 19,000 LB
GVWR	26,000
FRAME	STEEL
SUSPENSION	AIR RIDE
WHEELBASE	270"
TIRE SIZE	11R22.5
WHEELS	F STEEL / R STEEL
REAR D TYPE	ROLL-UP
R DOOR (IN X IN)	92X95
LIFT GATE MAKE	WALTCO
LIFT GATE MODEL	HLF 30
LIFT GATE CAPAC (LBS)	3000
EXTERIOR W (IN)	102
EXTERIOR L (FT)	26.0
AIR COND	YES, OPERATIONAL
INTERIOR COLOR	GREY
RADIO	AM/FM, OPERATIONAL
HIGH BACK SEATS	DRIVER SIDE ONLY
PASSENGER SEAT	STATIONARY
EXTERIOR COLOR	YELLOW
BUMPER	STAINLESS STEEL



BR	AKES
LEFT FRONT	RIGHT FRONT
COVERED	COVERED
LEFT REAR 1	RIGHT REAR 1
COVERED	COVERED
ADDITIONAL	BRAKE DETAIL
BRAKE DRUI	M IS COVERED


TIRES & WHEELS			
LEFT F	RONT	RIGHT	FRONT
10 / 32 BRIDGESTONE STEEL		16 / 32 FIRESTONE STEEL	
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
23 / 32	22/32	22 / 32	24 / 32
- STEEL	STEEL	- STEEL	- STEEL
FRONT TIRI	ES : 11R22.5	REAR TIRE	ES : 11R22.5


		GENERAL OBSERVATIONS
OII MILIOVO	NO	LICUTE WOR
OIL MILKY?	NO	LIGHTS WOR
OIL LEAKS?	YES	WIPERS WOR
WATER LEAKS?	NO	GAUGES WO
OIL IN COOLANT?	NO	AIR HORN WO
CLUTCH PLAY?	NA	CITY HORN V
STARTS?	YES	
DRIVES	YES	DIESEL PART

LIGHTS WORK?	YES - ALL
WIPERS WORK?	YES
GAUGES WORK?	YES - ALL
AIR HORN WORKS?	YES
CITY HORN WORKS?	YES

DIESEL PARTICULATE FILTER	PASS

DIAGNOSTIC	9 INACTIVE FAULTS FOUND - (SEE ECM REPORT)
BUMPER	SCRUBBED ON DRIVER SIDE
HOOD	CRACKED BY DRIVER HEADLIGHT
REAR DOOR	BENT IN MIDDLE
PAINT	MULTIPLE SCRATCHES AND DENTS AROUND BOX





REPORT DOCUMENTS