



Commercial Credit Group, Inc (Mark Wenzel)
525 N Tryon Street, Charlotte, NC 28202 USA
(704) 414-2456

VIN: 3HSDJSNR2HN447862
PO #: 15110

2017 INTERNATIONAL PROSTAR 122

SPECIFICATIONS	
MILEAGE	542,861 / 542,845 (ECM)
ENGINE HOURS	19,395
ENGINE	NAVISTAR N13 12.4L 450 HP
ENG BRAKE	YES
ENG SERIAL	2Y4412096
FUEL / TANKS	DIESEL - 2 ALUM 200 GAL TOTAL
EXHAUST	HORIZONTAL
TRANSMISSION	EATON FAOM-15810S-EN3 10 SPD AUTO
DRIVE OPTS	POWER STEERING, OVERDRIVE, CRUISE
REAR END	MERITOR 2.64
AXLE TYPE	TANDEM - F 12,350 LB / R 40,000 LB
GVWR	52,350
FRAME	STEEL
SUSPENSION	AIR RIDE
WHEELBASE	226"
TIRE SIZE	F 295 75R 22.5 / R 445 50R 22.5
WHEELS	F ALUMINUM / R ALUMINUM
WHEEL 5TH	AIR SLIDE
AIR COND	YES, OPERATIONAL
SLEEPER	72"
DUAL BUNK	YES
INTERIOR COLOR	GRAY
RADIO	AM/FM / CD, OPERATIONAL
MIRRORS	DUAL POWER
HIGH BACK SEATS	DUAL
PASSENGER SEAT	AIR RIDE
EXTERIOR COLOR	WHITE
BUMPER	PAINTED
EXTERIOR OPTS	HEATED MIRRORS, FULL FAIRINGS



BRAKES	
LEFT FRONT	RIGHT FRONT
DISC	DISC
LEFT REAR 1	RIGHT REAR 1
DISC	DISC
LEFT REAR 2	RIGHT REAR 2
DISC	DISC
ADDITIONAL BRAKE DETAIL	
DISC TYPE	

TIRES & WHEELS			
LEFT FRONT		RIGHT FRONT	
6 / 32 ALUMINUM		14 / 32 ALUMINUM	
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
25 / 32 YOKOHAMA ALUMINUM	-	-	25 / 32 YOKOHAMA ALUMINUM
LEFT OUTER 2	LEFT INNER 2	RIGHT INNER 2	RIGHT OUTER 2
4 / 32 - ALUMINUM	-	-	25 / 32 - ALUMINUM
FRONT TIRES: 295 75R 22.5		REAR TIRES: 445 50R 22.5	

ADDITIONAL TIRE DETAIL
DOUBLE COIN BRAND ON STEERS

GENERAL OBSERVATIONS			
OIL MILKY?	NO	LIGHTS WORK?	YES - ALL
OIL LEAKS?	NO	WIPERS WORK?	YES
WATER LEAKS?	NO	GAUGES WORK?	YES - ALL
OIL IN COOLANT ?	NO	AIR HORN WORKS?	YES

CLUTCH PLAY?	NA	CITY HORN WORKS?	YES
STARTS?	YES		
DRIVES	YES	DIESEL PARTICULATE FILTER	PASS

WEAR & TEAR DETAIL

DIAGNOSTICS	1 ACTIVE AND 11 INACTIVE CODES - SEE ATTACHED REPORT
PAINT	VARIOUS CHIPS AND SCRATCHES
HOOD	RIGHT SIDE SPOT MIRROR MISSING
HOOD	HOLES FROM PREVIOUS INSTALLED EQUIPMENT - RIGHT SIDE FENDER
MUD FLAP	RIGHT SIDE MISSING
SIDE FAIRINGS	MISSING TRIM STRIPS
SEATS	UPHOLSTERY DIRTY AND WORN.
TIRES	2 TIRES, WORN BELOW 10/32. LRR OUTSIDE TIRE IS FLAT

REPORT PHOTOS





Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services
101 W. Shrader St. Liberty, MO 64068
www.nationalinspect.com