

# National Inspection Services

Report: 274626 09/13/2024

VIN: 3ALACWDT3HDHV3972

PO #: 15143

#### Commercial Credit Group, Inc (Mark Wenzel) 525 N Tryon Street, Charlotte, NC 28202 USA (704) 414-2456

## 2017 FREIGHTLINER M2

GENERAL OBSERVATIONS

	SPECIFICATIONS
MILEAGE	201,078 / 201,079 (ECM)
ENGINE HOURS	5,229
ENGINE	CUMMINS ISB 6.7 220 HP
ENG SERIAL	58648240
FUEL / TANKS	DIESEL - 1 ALUM 80 GAL TOTAL
TRANSMISSION	ALLISON 2200 RDS 8 SPD AUTO
DRIVE OPTS	POWER STEERING, OVERDRIVE, CRUISE
REAR END	DETROIT 5.56
AXLE TYPE	SINGLE - F 10,000 LB / R 19,000 LB
GVWR	26,000
FRAME	STEEL
SUSPENSION	AIR RIDE
WHEELBASE	270"
TIRE SIZE	11R22.5
WHEELS	F ALUMINUM / R ALUMINUM
REAR D TYPE	ROLL-UP
R DOOR (IN X IN)	94W X 96H
LIFT GATE MAKE	PALFINGER
LIFT GATE CAPAC (LBS)	3300
INTERIOR H (IN)	102
EXTERIOR W (IN)	102
EXTERIOR L (FT)	26.0
AIR COND	YES, OPERATIONAL
INTERIOR COLOR	GRAY
RADIO	AM/FM, OPERATIONAL
HIGH BACK SEATS	DUAL
PASSENGER SEAT	STATIONARY
EXTERIOR COLOR	YELLOW
BUMPER	PAINTED
EXTERIOR OPTS	HEATED MIRRORS



BRAKES		
LEFT FRONT	RIGHT FRONT	
COVERED	COVERED	
LEFT REAR 1	RIGHT REAR 1	
COVERED	COVERED	

TIRES & WHEELS			
LEFT FRONT		RIGHT FRONT	
11/32 BRIDGESTONE ALUMINUM		12 / 32 BRIDGESTONE ALUMINUM	
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
13 / 32 CONTINENTAL	13 / 32 CONTINENTAL	14 / 32 BR <b>I</b> DGESTONE	14 / 32 BRIDGESTONE
ALUMINUM	ALUMINUM	ALUMINUM	ALUMINUM
FRONT TIR	RES: 11R22.5	REAR TIR	<b>ES</b> : 11R22.5

NO
NO
NO
NO
NA
YES
YES

LIGHTS WORK?	YES - ALL
WIPERS WORK?	YES
GAUGES WORK?	YES - ALL
AIR HORN WORKS?	YES
CITY HORN WORKS?	YES


DIESEL PARTICULATE FILTER	FAIL
---------------------------	------


### ADDITIONAL OBSERVATIONS

#### ACTIVE AFTERTREATMENT FAULT

WEAR & TEAR DETAIL	
DIAGNOSTICS	2 ACTIVE / 31 INACTIVE FAULTS DETECTED - (SEE ECM REPORT)
HOOD	HOOD HAS DAMAGE BY DRIVER SIDE OF GRILLE
REAR DOOR	INSIDE OF DOOR PANEL BREAKING AWAY.

BODY HAS LIGHT SCRATCHES ABND BLEMISHES THROUGHOUT





### REPORT DOCUMENTS

 $Condition\ report\ only.\ National\ Inspection\ Services\ does\ not\ guarantee\ mechanical\ reliability.$ 

© National Inspection Services 101 W. Shrader St. Liberty, MO 64068 www.nationalinspect.com