

---

**Collateral**

Year: 2023	Make: kenworth	Model: t880 triaxle	Color:
VIN #: ***BDR-F-B146976	Mileage: N/A	License/St: au37911	Expiration:

---

<b>General</b>	<b>General Condition</b>	<b>Mechanical Condition</b>	<b>Interior Condition</b>
	Average	Average	Dirty

Notes:

---

<b>Keys</b>	<b>Ignition Keys</b> No	<b>Secondary Keys</b> No	<b>Battery</b> None
-------------	-------------------------	--------------------------	---------------------

**Options**

<b>Type Of Vehicle</b>	<b>Roof</b>	<b>Transmission</b>	<b>Stereo</b>
_____	Standard Roof	Manual	Am/fm
<input checked="" type="checkbox"/> Power Windows	<input checked="" type="checkbox"/> Power Locks	<input checked="" type="checkbox"/> Tilt Wheel	<input checked="" type="checkbox"/> A/C
<input type="checkbox"/> Power Seats	<input type="checkbox"/> Power Steering	<input type="checkbox"/> Cruise Control	<input type="checkbox"/> Diesel
<input checked="" type="checkbox"/> Leather Seats	<input type="checkbox"/> Alloy Wheels	<input type="checkbox"/> Camper Shell	<input type="checkbox"/> Rear A/C

Details:

---

<b>Condition</b>	<b>Body</b>	<b>Paint</b>	<b>Able To Drive</b>
	Average	Scratched	No Keys

**Driver's Side**

Front Quarter Panel	Front Door	Rear Door	Rear Quarter Panel	P/U Bed
Scratched And Dinged	Scratched And Dinged	N/a	Scratched And Dinged	N/a

**Passenger's Side**

Front Quarter Panel	Front Door	Rear Door	Rear Quarter Panel	P/U Bed
Scratched And Dinged	Scratched And Dinged	N/a	Scratched And Dinged	N/a

---

<b>Top</b>	<b>Hood</b>	<b>Roof</b>	<b>Tailgate</b>
	Scratched And Dinged	Scratched And Dinged	Scratched And Dinged

---

<b>Bumper</b>	<b>Front</b>	<b>Rear</b>
	Scratched And Dinged	Scratched And Dinged

---

<b>Glass</b>	Scratched
--------------	-----------

---

<b>Tires</b>	<b>Left Rear</b>	<b>Right Front</b>	<b>Right Rear</b>	<b>Spare</b>
<b>Left Front</b>	Average	Average	Average	None
Average				
<b>Wheel Cover Count</b>				
_____				

---

Completed By:	Received By:_____
<b>Date: 12/03/2024</b>	Received On:_____